

## **HID Xenon Conversion Kit Troubleshooting**

Turborevs HID Xenon Conversion Kit Trouble Shooting page is designed to assist you with the basic checks of the electrical system.

**Symptom: HID kit will not light up.**

**A.) Possible Cause: Connections the wrong way round.**

Solutions: Ensure the plug connector is plugged in the correct way as shown in the pictures below.



Also ensure the red and black spade connections are connected the correct way, red is 12v and will be generally connected to yellow wire on the car (use a multimeter to check which is 12v on your car), and black

is connected to 0v.



### **B.) Possible Cause: Bulb blown**

Solutions: Swap the bulbs around (leave the ballast boxes as they are), if the fault stays on the same side the problem will be the ballast box, if the fault moves with the bulb the problem will be the bulb.

### **D.) Possible Cause: Lights are flickering.**

Solutions: Ensure you have bought the correct kit for your car you may need some additional error cancellers.

If you have not found the answer to your problem for your HID Xenon HID kit please email: [sales@turborevs.org.uk](mailto:sales@turborevs.org.uk)

To purchase spare bulbs and ballasts for your HID Xenon Kit please see our website [www.turborevs.org.uk](http://www.turborevs.org.uk)